


Inspection Report


Inspection Date:	Nov 25,2013
Factory Name:	SHENZHEN MARK TRADING CO.,LTD
Factory Address:	SHENZHEN,GUANGDONG
Item/Product No.:	Refer to the below item no
Order Quantity:	54500pcs
Sample Size:	500pcs
Result	Fail

1.	Regarding item no HDC-251BK/PRC-201, The factory didn't provided tool to do function test.
2.	Regarding item no SEL-302BK, the actual fan size is 15cm . but the requirement is 20cm on gift box .
3.	Regarding item no HS-307, the marking is wrong .
4.	Regarding Item no NSL-101/NSL-201,The factory only allow to inspect 9pcs /item no


Photos to follow



Remark 2(actual fan size is 15cm)



Remark 2(actual fan size is 15cm)



Remark 2(requirement size)



Remark 3(actual marking)

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 2 of 109



Remark 3(actual marking)	
--------------------------	--

Order Quantity:		54500pcs		Total Order Number of Export Cartons:				502		
Total number of selected export carton:		31CTNS		Carton Numbers Sampled		N/A				
P.O. No.	Item No.	Order Qty (PCS)	Order Qty (CTN)	Inspection Qty (PCS)		No of selected export carton	Sample Size	No of Defects For Sample		
				Packed	Not Packed			CR	MA	MI
	HB-101	5000	50	5000	0	2	50	Refer to the below AQL		
	HS-307	3000	75	3000	0	4	35			
	HDP-602	3000	75	3000	0	4	32			
	EB-101	3000	15	3000	0	2	32			
	SEL-302BK	1000	50	1000	0	5	10			
	HDC-251BK	1000	10	1000	0	2	10			
	STC-101	10000	34	10000	0	2	95			
	SCE-101	10000	20	10000	0	2	95			
	PLC-201	5000	15	5000	0	2	48			
	PRC-201	1500	8	1500	0	2	18			
	RCA-201	6000	30	6000	0	2	57			
	NSL-101	3000	60	3000	0	1	9			
	NSL-201	3000	60	3000	0	1	9			

General Inspection Level - Workmanship / Visual/Function	G-II	AQL - Critical Defectives: Expected hazard of human life, health or environment	0.0
[X] Normal Inspection [] Reduced Inspection [] Tightened Inspection		AQL - Functional	0.0
		AQL - Major Defectives: Usability or life time probably significant affected	1.0

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561 Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net			
Report Date:	Project No.:	Report No.:	Page 3 of 109

Sample Size – CRI/FUN/MAJ/MIN:	500pcs/500pcs/500pcs	AQL - Minor Defectives: Usability or life time probably less or not affected	1.5
--------------------------------	----------------------	--	-----

DESCRIPTION	CR	MA	MI
SCRATCH MARK (HDP-602)			8
Carton damage (HDP-602)			2
POOR PAINTING (HDP-602)			3
Carton damage (NS-201)			2
No function(NSL-101)	1		
No function(HS-307)		1	
Uncut thread end (HS-307)			1
Dirty mark (HB-101)			1
Scratch mark (HB-101)			1
Deform (RCA-201)			1
Total Found:			
AC/RE	0/1	10/11	14/15
Result	Fail	pass	Fail

Defective photos to follow

HDP-602


	
Carton damage	Carton damage

Report Date:

Project No.:

Report No.:


Page 4 of 109



Poor painting




Poor painting



Poor painting



Scratch mark




Scratch mark



Scratch mark

Report Date:	Project No.:	Report No.:	Page 5 of 109
--------------	--------------	-------------	---------------



Scratch mark



Scratch mark



Scratch mark



Scratch mark



Scratch mark

N/A

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 6 of 109




Carton damage

Carton damage






N/A

No function



HS-307

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 7 of 109

No function	Uncut thread end
HB-101	
	
Dirty mark	Scratch mark
RCA-201	
	N/A
Deform	

INNER & MASTER PACKAGING						
Item No.	Product Dimension (Cm)	Master Package Dimension And Weight				
		Length (cm)	Width (cm)	Height (cm)	G.W. (KGS)	Product Weight (g)
HB-101	L:200cm	71.5	36.5	58	13.91	73
HS-307	L:176cm	64	50	40.3	10.6	158.5
HDP-602	L:118cm	68	45.5	43	14.13	150
EB-101	Wire length:122cm	53.5	34	43	8.74	110
SEL-302BK	32.5x27.5cm	57.5	37	35.5	18.36	760.5

HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 8 of 109

HDC-251BK	12.5x7.5cm	46.5	38,5	55	14.47	75
STC-101	L:49.5cm	47	31	30.5	7.346	14
SCE-101	L:15.5cm	47	31	30.5	7.764	6
PLC-201	L:154cm	46.5	31	30.5	11.204	22
PRC-201	L:121cm	46	31	30.5	8.888	34
RCA-201	L:149cm	47	31	30	8.86	38
NSL-101	L:183cm	56	35	23	9.5	140
NSL-201	L:180cm	55	35	23	10.17	150



HDP-602

Report Date:

Project No.:

Report No.:

Page 9 of 109



Report Date:

Project No.:

Report No.:

Page 10 of 109




Report Date:

Project No.:

Report No.:

Page 11 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561

Address: Yulong garden, Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 12 of 109




Report Date:

Project No.:

Report No.:

Page 13 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 14 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561

Address: Yulong garden, Huoju development zone. Zhongshan, China



E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 15 of 109

**NSL-201**

HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China



E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 16 of 109



Report Date:

Project No.:

Report No.:

Page 17 of 109






Report Date:

Project No.:

Report No.:

Page 18 of 109



Report Date:

Project No.:

Report No.:

Page 19 of 109



N/A

NSL-101

HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 20 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 21 of 109






Report Date:

Project No.:

Report No.:

Page 22 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China



E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 23 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:


Project No.:

Report No.:

Page 24 of 109



EB-101



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561

Address: Yulong garden, Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 25 of 109





Report Date:

Project No.:

Report No.:

Page 26 of 109




Report Date:

Project No.:

Report No.:

Page 27 of 109



Report Date:

Project No.:

Report No.:

Page 28 of 109



N/A

HS-307

HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 29 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 30 of 109



Report Date:

Project No.:

Report No.:

Page 31 of 109







Report Date:

Project No.:

Report No.:

Page 32 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 33 of 109



Report Date:

Project No.:

Report No.:

Page 34 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 35 of 109



**HDC-251BK**

Report Date:

Project No.:

Report No.:

Page 36 of 109






Report Date:

Project No.:

Report No.:

Page 37 of 109



Report Date:

Project No.:

Report No.:

Page 38 of 109

EN Specifications:

- ▶ Color: Black
- ▶ Case Material: aluminium alloy
- ▶ Hard Disk Compatible: 2.5" I e II SATA HDD (9.5mm)
- ▶ Max. Transfer Rate: 480Mbps
- ▶ Support HDD up to: 3TB
- ▶ Connection: USB 2.0 and 1.1 version
- ▶ O.S. Compatibility: Windows 98/ME/2000/XP Vista/Win7/Win8 and Mac OS X 10.2 or later
- ▶ Measures: 123x75x13.3mm
- ▶ Weight: 0.05KG

PT Especificações:

- ▶ Cor: Preto
- ▶ Material do Case: liga de alumínio
- ▶ HD Compatível: HDD SATA I e II 2.5" (9,5mm)
- ▶ Taxa máx. de Transferência: 480Mbps
- ▶ Suporta HDD de até: 3TB
- ▶ Conexão: USB versão 2.0 e 1.1
- ▶ Sistema Operacional Compatível: Windows 98/ME/2000/XP Vista/Win7/Win8 e Mac OS X 10.2 ou anterior
- ▶ Dimensões: 123x75x13.3mm
- ▶ Peso: 0.05KG

PT Especificações:

- ▶ Cor: Preto
- ▶ Material do Case: liga de alumínio
- ▶ HD Compatível: HDD SATA I e II 2.5" (9,5mm)
- ▶ Taxa máx. de Transferência: 480Mbps
- ▶ Suporta HDD de até: 3TB
- ▶ Conexão: USB versão 2.0 e 1.1
- ▶ Sistema Operacional Compatível: Windows 98/ME/2000/XP Vista/Win7/Win8 e Mac OS X 10.2 ou anterior
- ▶ Dimensões: 123x75x13.3mm
- ▶ Peso: 0.05KG

EN Included items:

- ▶ 01 HDC-251 Slim Hard Disk Case
- ▶ 01 2xUSB/Mini USB cable
- ▶ 01 Protective cover
- ▶ 01 User Guide

PT Itens inclusos:

- ▶ 01 Case Slim para Disco Rígido HDC-251
- ▶ 01 Cabo 2xUSB/Mini USB
- ▶ 01 Capa protetora
- ▶ 01 Manual do usuário



www.fortrek.com.br

Garantia de 6 meses
contra defeito de fabricação

Importado por:
Hayamax Dist. de Prod. Elet. Ltda.
CNPJ: 01.725.627/0001-72

Origem: China



All mentioned trademarks and registered trademarks are property of their respective holders.
Todas as marcas e marcas registradas mencionadas são propriedade de seus respectivos detentores.



www.fortrek.com.br

COD: 52573 HDC-251



Report Date:

Project No.:

Report No.:

Page 39 of 109




Report Date:

Project No.:

Report No.:

Page 40 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 41 of 109





Report Date:

Project No.:

Report No.:

Page 42 of 109



N/A

SEL-302BK



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561

Address: Yulong garden, Huoju development zone. Zhongshan, China



E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 43 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561

Address: Yulong garden, Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 44 of 109





Report Date:

Project No.:

Report No.:

Page 45 of 109



Report Date:

Project No.:

Report No.:

Page 46 of 109




Report Date:

Project No.:

Report No.:

Page 47 of 109



Report Date:

Project No.:

Report No.:

Page 48 of 109



Report Date:

Project No.:

Report No.:

Page 49 of 109



HB-101



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 50 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 51 of 109




Report Date:

Project No.:

Report No.:

Page 52 of 109



Report Date:

Project No.:

Report No.:

Page 53 of 109

Technical Specifications

Speaker: 30mm
Impedance: 32 Ohms
Sensitivity: 105dB at 1KHz
Frequency: 20 ~ 20000Hz
Power: 100mW
Cable length: 1.80m
Connectors: 2 x stereo P2 (3.5 mm)
Microphone Sensitivity: -58dB ± 2dB

Included item:

HB-101 Multimedia Headset

Especificações Técnicas

Falantes: 30mm
Impedância: 32 Ohms
Sensibilidade: 105dB até 1KHz
Frequência: 20 ~ 20000Hz
Potência: 100mW
Comprimento do cabo: 1,80m
Conectores: 2 x P2 estéreo (3,5mm)
Sensibilidade do Microfone: -58dB ± 2dB

Item incluso:


Fone de Ouvido Multimídia HB-101

A LITE é uma linha desenvolvida pela Fortrek que tem como objetivo oferecer produtos de informática com recursos essenciais para utilização prática e eficiente. Conheça outros produtos desta linha no site www.liteseries.com.br.



CÓD.: 52568

All mentioned trademarks and registered trademarks are property of their respective holders.
Todas as marcas e marcas registradas mencionadas são propriedade de seus respectivos detentores.
Imagens ilustrativas / Illustrative images



Fortrek que tem como objetivo oferecer produtos de informática com recursos essenciais para utilização prática e eficiente. Conheça outros produtos desta linha no site www.liteseries.com.br.

CÓD.: 52568

HB-101



Garantia de 6 meses
contra defeito de fabricação

Importado por:
Hayamax Dist. de Prod. Elet. Ltda.
CNPJ: 01.725.627/0001-72

Origem: China

www.liteseries.com.br

Report Date:

Project No.:

Report No.:

Page 54 of 109



Report Date:

Project No.:

Report No.:

Page 55 of 109



STC-101

HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 56 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561

Address: Yulong garden, Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 57 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel: 13537374561


Address: Yulong garden, Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:	Project No.:	Report No.:	Page 58 of 109
--------------	--------------	-------------	----------------




Report Date:	Project No.:	Report No.:	Page 59 of 109
--------------	--------------	-------------	----------------



N/A

RCA-201



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 60 of 109




Report Date:

Project No.:

Report No.:

Page 61 of 109



Report Date:

Project No.:

Report No.:

Page 62 of 109



PRC-201



Report Date:

Project No.:

Report No.:

Page 63 of 109




Report Date:

Project No.:

Report No.:

Page 64 of 109





HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China


E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 66 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 67 of 109



Report Date:

Project No.:

Report No.:

Page 68 of 109



HS Inspection Services

Tel: +86 760 85337826, Tel:13537374561

Address:Yulong garden,Huoju development zone. Zhongshan, China

E-mail: hsinspection@hotmail.com Website: www.hsinspection.net

Report Date:

Project No.:

Report No.:

Page 69 of 109



Report Date:

Project No.:

Report No.:

Page 70 of 109




Report Date:

Project No.:

Report No.:

Page 71 of 109




Test pictures

HDP-602

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 72 of 109




Carton size



Carton size




Carton size



Carton size



Carton size



Carton size



GW



GW



Product weight




Product weight



Wire size check



Wire size check


HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 74 of 109
			
Barcode test		Barcode test	
			
Drop test		Function test	
			
3M tape test		3M tape test	
NSL-201			

Report Date:


Project No.:

Report No.:

Page 75 of 109




Carton size check



Carton size check




Carton size check



Carton size check



Carton size check



Carton size check

Report Date:

Project No.:

Report No.:

Page 76 of 109



GW



GW



Product weight



Product weight



Function test




Drop test

Report Date:

Project No.:

Report No.:

Page 77 of 109



Product size check

Product size check

NSL-101




Carton size check

Carton size check

Report Date:	Project No.:	Report No.:	Page 78 of 109
--------------	--------------	-------------	----------------




Carton size check



Carton size check



Carton size check



Carton size check



GW




GW

Report Date:	Project No.:	Report No.:	Page 79 of 109
--------------	--------------	-------------	----------------



Barcode test



Barcode test




Drop test



Function test



Product size check



Product size check

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 80 of 109



Product weight



Product weight



Function test

N/A

EB-101



Carton size check




Carton size check

Report Date:	Project No.:	Report No.:	Page 81 of 109
--------------	--------------	-------------	----------------



Carton size check



Carton size check



Carton size check



Carton size check



GW



GW




Product weight



Drop test




3M tape test



3M tape test



Barcode test




Barcode test

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 83 of 109



Product size check



Product size check



Function test

N/A

HS-307



Carton size check



Carton size check

Report Date:


Project No.:

Report No.:

Page 84 of 109




Carton size check



Carton size check



Carton size check



Carton size check



GW



GW

Report Date:

Project No.:

Report No.:

Page 85 of 109



Product weight



Drop test



Product size check



Product size check



3M tape test




3M tape test

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 86 of 109

		N/A	
---	--	------------	--


Function test .

HDC-251BK

			
--	--	---	--

Carton size check

Carton size check

			
---	--	--	--

Carton size check

Carton size check

Report Date:


Project No.:

Report No.:

Page 87 of 109



Carton size check



Carton size check



GW



GW



Product weight




Product weight

Report Date:	Project No.:	Report No.:	Page 88 of 109
--------------	--------------	-------------	----------------




Product size check



Product size check




Product size check



Product size check



Barcode test



Barcode test

Report Date:	Project No.:	Report No.:	Page 89 of 109
--------------	--------------	-------------	----------------



3M tape test



3M tape test



N/A

SEL-302BK



Carton size check




Carton size check

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 90 of 109



Carton size check



Carton size check



GW



GW

Report Date:	Project No.:	Report No.:	Page 91 of 109
--------------	--------------	-------------	----------------




Product weight



Product weight



Product size check



Product size check



Product size check



Product size check

Report Date:


Project No.:

Report No.:

Page 92 of 109



Barcode test



Barcode test



3M tape test



3M tape test



Function test .

N/A

Report Date:	Project No.:	Report No.:	Page 93 of 109
--------------	--------------	-------------	----------------



Carton size check



Carton size check



Carton size check



Carton size check



Carton size check



Carton size check

Report Date:

Project No.:

Report No.:

Page 94 of 109



GW




GW




Product weight



Drop test




Barcode test



Barcode test


HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 95 of 109

	
Product size check	Product size check
	N/A
Function test	
STC-101	
	
Carton size check	Carton size check

Report Date:	Project No.:	Report No.:	Page 96 of 109
--------------	--------------	-------------	----------------




Carton size check



Carton size check



Carton size check



Carton size check



GW




GW

Report Date:

Project No.:

Report No.:


Page 97 of 109



Product size check



Product size check




Barcode test



Barcode test



Drop test




Function test

Report Date:

Project No.:

Report No.:

Page 98 of 109



Function test



Function test


RCA-201



Carton size check




Carton size check






Carton size check



Carton size check



GW



GW



Product weight




Drop test

Report Date:

Project No.:

Report No.:


Page 100 of 109




Barcode test




Barcode test




Product size check



Product size check



Function test



Function test

Report Date:

Project No.:

Report No.:

Page 101 of 109




Carton size check



Carton size check



Carton size check



Carton size check




Carton size check



Carton size check



GW




GW




Product weight



Drop test



Product size check



Product size check

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 103 of 109



Barcode test


Barcode test

SCE-101



Carton size check

Carton size check



Carton size check

Carton size check

Report Date:

Project No.:

Report No.:

Page 104 of 109



Carton size check



Carton size check



GW



GW



Product weight




Drop test

Report Date:


Project No.:

Report No.:


Page 105 of 109



Product size check




Product size check




Barcode test



Barcode test



Function test



Function test

Report Date:

Project No.:

Report No.:

Page 106 of 109



Carton size check



Carton size check




Carton size check



Carton size check



Carton size check



Carton size check

Report Date:

Project No.:

Report No.:

Page 107 of 109



GW



GW




Product weight



Drop test




Product size check



Function test

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 108 of 109



Barcode test



Barcode test

OTHER PICTURES



Carton in stock



Carton in stock



Carton in stock



Carton in stock

HS Inspection Services Tel: +86 760 85337826, Tel:13537374561		Address:Yulong garden,Huoju development zone. Zhongshan, China E-mail: hsinspection@hotmail.com Website: www.hsinspection.net	
Report Date:	Project No.:	Report No.:	Page 109 of 109



Carton in stock	5ply
-----------------	------

End of Inspection Report